

# Using Cisco 7900/8800/9900 phones

This page reorganizes the operational steps for **Using Cisco 7900/8800/9900 phones**.

Standard asterisk support for these legacy phones is not complete, so it is needed to apply a series of patches:

<http://usecallmanager.nz/sip-conf.html>

## Current Verification

After applying the change, verify the related MiRTA PBX page, the Asterisk logs, and the relevant Status menu entry. Recheck tenant selection before testing tenant-specific behavior.

---

Revision #3

Created 2026-06-02 21:59:55 UTC by Admin

Updated 2026-06-02 22:00:37 UTC by Admin